

## EPA Official Record

**Notes ID:** 4BEECCFAE744EFAFB416FBA6D95E0284

**From:** "Page, Elizabeth" <Elizabeth.Page@kochind.com>

**To:** Brandon Perkins/R10/USEPA/US@EPA

**Copy To:** "Knowles, Daren" <Daren.Knowles@fhr.com>

**Delivered Date:** 05/03/2011 11:08 AM PST

**Subject:** RE: Requested Reports - Flint Hills Resources Alaska

Brandon,

Please find attached the Work Plan. We are evaluating data from the investigation and the results will be presented to ADEC as a section in the Site Characterization Report due on May 31, 2011.

Let me know if you have any other questions.

Liz

Elizabeth Page, P.G.

(817) 842-9070 TX Office

(907) 490-6226 ext. 326 NPR Office

(817) 723-4616 Cell

602 Strada Circle, Suite 121. Mansfield, TX 76063

Every great mistake has a halfway moment, a split second when it can be recalled and perhaps remedied. Pearl S. Buck

-----Original Message-----

From: Perkins.Brandon@epamail.epa.gov

[mailto:Perkins.Brandon@epamail.epa.gov]

Sent: Friday, April 29, 2011 1:28 PM

To: Page, Elizabeth

Cc: Knowles, Daren

Subject: RE: Requested Reports - Flint Hills Resources Alaska

Hi Liz

I was wondering if you had an update on this work? Am I able to get a copy of the sampling work plan and sampling report, if it's available.

Thank you

Brandon Perkins

Office of Environmental Cleanup

U.S. Environmental Protection Agency, Region 10

206-553-6396

From: "Page, Elizabeth" <Elizabeth.Page@kochind.com>

To: Brandon Perkins/R10/USEPA/US@EPA

Cc: "Knowles, Daren" <Daren.Knowles@fhr.com>

Date: 12/28/2010 11:12 AM

Subject: RE: Requested Reports - Flint Hills Resources Alaska

Brandon,

Enclosed is information on your question regarding the schedule for the investigation of the laboratory sump system:

On December 15, 2010, we met with Brian Jackson of ADEC at the lab to discuss our proposed sampling locations. He indicated general agreement and asked that we prepare a sampling work plan.

On January 10, 2011, our implementation contractor will visit the lab to obtain site-specific information necessary to write the sampling work plan and plan the safe collection of the samples. We expect to have a sampling work plan ready for submittal to ADEC by early February.

If the sampling work plan works through the review and approval process fairly quickly, we can expect to be in the field by late February.

You also asked about the specific location of the lab within the refinery. Please reference Figure 3 of the September 2010 Site Characterization Work Plan. The lab is the building located on the Northeast corner of Tank Farm Road and Process Avenue.

If you have any other questions, please let me know.

Thanks,  
Liz

---

PLEASE NOTE:

New Street Address and Phone Number Below

Elizabeth Page, P.G.

Reiss Remediation, LLC

602 Strada Circle, Suite 121

Mansfield, TX 76063

Direct: (817) 842-9070

Fax: (817) 842-9110

Cell: (817) 723-4616

-----Original Message-----

From: Perkins.Brandon@epamail.epa.gov [  
mailto:Perkins.Brandon@epamail.epa.gov]

Sent: Monday, December 27, 2010 5:54 PM

To: Page, Elizabeth

Cc: Knowles, Daren

Subject: Re: Requested Reports - Flint Hills Resources Alaska

Hi Elizabeth

Thank you for sending these documents to me. Do you have an idea of when the additional investigation of the the lab drains will be conducted and complete? I'm also trying to determine where on the facility the laboratory is located. Is there a map or figure with its location?

Brandon Perkins, Site Assessment Manager Office of Environmental Cleanup  
U.S. Environmental Protection Agency, Region 10  
206-553-6396

From: "Page, Elizabeth" <Elizabeth.Page@kochind.com>

To: Brandon Perkins/R10/USEPA/US@EPA

Cc: "Knowles, Daren" <Daren.Knowles@fhr.com>

Date: 12/21/2010 03:12 PM

Subject: Requested Reports - Flint Hills Resources Alaska

Brandon,

During the TPT meeting on December 14, 2010, you requested copies of the attached reports related to investigations performed around the FHRA laboratory in North Pole, AK.

Lab Sump Piping Failure Investigation Report, dated July 21, 2010 (CO-092\_10.pdf)

Lab Sump Piping Failure Investigation Report Attachments, dated July 21, 2010 (CO-092-10 Attachments.pdf)

Sump Investigation Report and Investigation Closure Request, dated December 8, 2010 (CO-174-10 Sump Report.pdf)

Please let me know if you have any questions.

Thanks,

Liz

---

PLEASE NOTE:

New Street Address and Phone Number Below

Elizabeth Page, P.G.

Reiss Remediation, LLC

602 Strada Circle, Suite 121

Mansfield, TX 76063

Direct: (817) 842-9070

Fax: (817) 842-9110

Cell: (817) 723-4616

[attachment "CO-092-10.pdf" deleted by Brandon Perkins/R10/USEPA/US]

[attachment "CO-092-10 Attachments.pdf" deleted by Brandon

Perkins/R10/USEPA/US] [attachment "CO-174-10\_Sump Report.pdf" deleted by Brandon Perkins/R10/USEPA/US]



- FHRA Lab Investigation Work Plan\_031711.pdf